

Customer	Vehicle Owner	responsible Vehicle expert

inspection conditions

support of the car seller	yes
weather conditions	dry
lighting conditions	daylight
vehicle surface	dry/clean
access to the vehicle	accessible from all sites
underbody panelling	available - undamaged
lifting platform / pothole / ramp	available and used
test drive completed	yes
Why wasn't it possible to do a test drive?	

vehicle

vehicle identification number (VIN)	WBALM31000E4546	producer	BMW	model	Z4
construction/design type	coupé	number of doors	2 doors	gearbox	automatic transmission
next general inspection	05/20	pollutant class	Euro 5	motor fuel	petrol
mileage	63.378	first registration	2011	previous owners	2
previous usage	one-year-old car	performance in kW	150	cubic capacity	2497
keys	2 with remote control	colour	schwarz	type of automotive paint/lacquer	metallic
smell	alright	seats	2		

alright (*1) small damage (*2) severe damage (*3) non-existent (*4) not assessable (*5)

vehicle documents

<input checked="" type="radio"/> permits	non-existent/ was not available at the time of evaluation
<input checked="" type="radio"/> registration cert. Pt 1 / vehicle licence	original
<input checked="" type="radio"/> registration cert. Pt 2 / vehicle registration document	original
<input checked="" type="radio"/> service booklet	original
<input checked="" type="radio"/> log book/ radio code/ navigation software (CD)	original
<input checked="" type="radio"/> type approval	original
<input checked="" type="radio"/> HU/AU report	original

customer service/repairs

date	mileage	inspection mode	Who did the servicing?
05.04.2013	18	small inspection	authorized garage
05.05.2015	35	complete vehicle inspection	authorized garage
05.05.2017	47	small inspection	authorized garage
04.06.2019	63	complete vehicle inspection	authorized garage

remarks regarding customer services/repairs

tires	producer	usage	size	profile thickness in mm	remark
● front left mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● front right mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● back left mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● back right mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	porous
● spare wheel					

paint thickness	paint layer thickness in µm	condition
● engine bonnet	135	stone chipping
● mudguard front right	110	
● door front/right	110	
● door back/right		
● side wall/fender back/right	105	alright
● rear lid	110	
● fender back left	150	repaired damage caused by an accident
● door back/left		
● door front/left	1135	repaired damage caused by an accident
● mudguard front left	130	repaired damage caused by an accident
● roof	125	alright

state of the vehicle at the time of inspection - interior - interior visual inspection	
● security belts	
● steering wheel	
● instruments/ dashboard	
● air conditioner	
● heater/ air filter	
● sunroof/electric hood	
● operating elements	
● window lifter	
● rear view mirror	
● seats in front	
● seats behind	
● storage places/ gloves compartment	
● radio	
● floor covering	
● interior disguising	
● headliners	
● signal horn	

state of the vehicle at the time of inspection - lights	
<input checked="" type="checkbox"/> headlight	
<input checked="" type="checkbox"/> backlight	
<input checked="" type="checkbox"/> brakelight	
<input checked="" type="checkbox"/> reversing light	
<input checked="" type="checkbox"/> indicator	
<input checked="" type="checkbox"/> hazard lights	
<input checked="" type="checkbox"/> fog lamp	
<input checked="" type="checkbox"/> Abblendlicht	
<input checked="" type="checkbox"/> interior lights	
<input checked="" type="checkbox"/> daytime running lamp	

state of the vehicle at the time of inspection - exterior	
<input checked="" type="checkbox"/> rims	VR, VL, HR geschürft
<input checked="" type="checkbox"/> sealings	
<input checked="" type="checkbox"/> windshield	
<input checked="" type="checkbox"/> window glazing	
<input checked="" type="checkbox"/> windscreen wiper	
<input checked="" type="checkbox"/> car locks/ central locking system	
<input checked="" type="checkbox"/> general state of automotive paint	
<input checked="" type="checkbox"/> recognizable repainting	
<input checked="" type="checkbox"/> attached parts	
<input checked="" type="checkbox"/> exterior mirror	

state of the vehicle at the time of inspection - exterior cover	
<input checked="" type="checkbox"/> front bumpers	leicht geschürft; leichter Steinschlag
<input checked="" type="checkbox"/> grill	
<input checked="" type="checkbox"/> engine bonnet	Steinschlag; leichter Kratzer (poliert)
<input checked="" type="checkbox"/> roof	in Ordnung
<input checked="" type="checkbox"/> rear lid	
<input checked="" type="checkbox"/> side wall/fender back/left	reparierter Unfallschaden
<input checked="" type="checkbox"/> door back/left	nicht vorhanden
<input checked="" type="checkbox"/> door sill left	
<input checked="" type="checkbox"/> door front/left	reparierter Unfallschaden
<input checked="" type="checkbox"/> mudguard front left	reparierter Unfallschaden
<input checked="" type="checkbox"/> mudguard front right	
<input checked="" type="checkbox"/> door front/right	
<input checked="" type="checkbox"/> door sill right	
<input checked="" type="checkbox"/> door back/right	nicht vorhanden
<input checked="" type="checkbox"/> side wall/fender back/right	
<input checked="" type="checkbox"/> back bumpers	
<input checked="" type="checkbox"/> gap dimensions	

state of the vehicle at the time of inspection - underbody view (as far as testable)	
<input checked="" type="checkbox"/> steering linkage	
<input checked="" type="checkbox"/> steering gear	
<input checked="" type="checkbox"/> control arm	
<input checked="" type="checkbox"/> wheel suspension	
<input checked="" type="checkbox"/> anti-roll bar front/back	
<input checked="" type="checkbox"/> shock absorber	
<input checked="" type="checkbox"/> springs	
<input checked="" type="checkbox"/> wheel bearing	
<input checked="" type="checkbox"/> brake cables/hose	
<input checked="" type="checkbox"/> brake disc	
<input checked="" type="checkbox"/> brake pad	
<input checked="" type="checkbox"/> brake line	
<input checked="" type="checkbox"/> brake abrasion	
<input checked="" type="checkbox"/> condition of the exhaust system	
<input checked="" type="checkbox"/> exhaust manifold	
<input checked="" type="checkbox"/> oil density gear	
<input checked="" type="checkbox"/> oil density engine	
<input checked="" type="checkbox"/> oil density differential	
<input checked="" type="checkbox"/> state of the underbody (general)	

state of the vehicle at the time of inspection - engine compartment view	
<input checked="" type="checkbox"/> motor oil state	
<input checked="" type="checkbox"/> brake fluid - state	
<input checked="" type="checkbox"/> cooler status	
<input checked="" type="checkbox"/> fuel system	
<input checked="" type="checkbox"/> battery casing/ fixing	

state of the vehicle at the time of inspection - test run of the propulsion engine	
<input checked="" type="checkbox"/> starter	
<input checked="" type="checkbox"/> clutch	nicht vorhanden
<input checked="" type="checkbox"/> motor running	
<input checked="" type="checkbox"/> functioning of the instruments	
<input checked="" type="checkbox"/> conspicuous noises	
<input checked="" type="checkbox"/> conspicuous noises timing chain	

conditions during the test drive	
was carried out on	13:00
highest speed achieved	50
was carried out in/on the	city
conspicuous features?	keine

state of the vehicle at the time of inspection - test drive	
<input checked="" type="radio"/> clutch	Nicht prüfbar
<input checked="" type="radio"/> steering	
<input checked="" type="radio"/> gearbox	
<input checked="" type="radio"/> conspicuous noises	
<input checked="" type="radio"/> functioning of instruments	
<input checked="" type="radio"/> directional stability	
<input checked="" type="radio"/> brake system responsivity	
<input checked="" type="radio"/> load change	
<input checked="" type="radio"/> motor running	
<input checked="" type="radio"/> braking action	
<input checked="" type="radio"/> accelerator	
<input checked="" type="radio"/> gear change	
error in instrument cluster	
No failures were displayed in the electronic instrument cluster.	
existing / known accident damage	
The following traces of accidents were found: Seitenwand-Kotflügel h. l. - reparierter Unfallschaden Tür v. l. - reparierter Unfallschaden Kotflügel v. l. - reparierter Unfallschaden	
Conclusion of the expert:	
The following damages were identified: Außen - Felgen - leichter Mangel - VR, VL, HR geschürft Karosserie Sicht - Stoßfänger vorn - leichter Mangel - leicht geschürft; leichter Steinschlag Karosserie Sicht - Motorhaube - leichter Mangel - Steinschlag; leichter Kratzer (poliert) No impairment of road safety was found. The vehicle possesses traces of use corresponding to the age and mileage.	

The inspection was carried out without exposing the assemblies or dismantling work. There remains a risk of hidden defects or accidental damage.

Important: The condition report of the vehicle was prepared to the best of the expert's knowledge and belief at the time of the inspection under the given possibilities. The report does not establish any liability towards the inspector nor does it contain any guarantee for the buyer or seller. All components/groups not expressly listed will not be assessed as part of the inspection. The inspection is always carried out without disassembly work or disassembly of parts. Not all conceivable load and operating conditions can be achieved within the scope of the visual and functional inspection of the individual components and the test run and therefore not all possible existing defects can be detected within the scope of this inspection. They also depend, among other things, on the prevailing weather and inspection conditions.

intermediary: diepruefer.de GmbH / Schillerstraße 1 / 07745 Jena

Das Gutachten wurde am 06.06.2019 um 10:54 Uhr erstellt.

(*1) – In Ordnung - alright = the signs of usage correspond to the age and mileage

(*2) – leichter Mangel- small damage = impairments regarding the value and appearance

(*3) – schwerer Mangel - severe damage = impairments regarding the functionality and security of the vehicle

(*4) – nicht vorhanden - non-existent = does not exist as a part of the vehicle

(*5) – nicht prüfbar - not assessable = could not be assessed properly due to the insufficient conditions

VL (v.l.) – front left

VR (v.r.) – front right

HL (h.l.) – back left

HR (h.r.) – back right

Valuation

Value on the market: €13,800.00

The vehicle values determined take into account the date of first registration or the year of construction, the mileage or the operating hours, as well as the general condition and the damage found that go beyond normal use (see table of excess and reduced values below). In addition, the market situation of the vehicle on the valuation date was included in the valuation.

Depreciation / repair costs			
Designation / type of repair	remark	Estimated cost of repair	Decreased value
Seitenwand-Kotflügel h. l.		€50.00	
Seitenwand-Kotflügel h. r.		€50.00	
Unten Sicht (soweit prüfbar) - Bremsscheiben - leichter Mangel - leichte Rillenbildung / Rostansatz	behebt sich durchs fahren		€0.00

all values including VAT

Werterhaltende/werterhöhende Maßnahmen:
The expert did not have any information about value-increasing or value-maintaining repair expenses.

Important: The condition report of the vehicle was prepared to the best of the expert's knowledge and belief at the time of the inspection under the given possibilities. The report does not establish any liability towards the inspector nor does it contain any guarantee for the buyer or seller. All components/groups not expressly listed will not be assessed as part of the inspection. The inspection is always carried out without disassembly work or disassembly of parts. Not all conceivable load and operating conditions can be achieved within the scope of the visual and functional inspection of the individual components and the test run and therefore not all possible existing defects can be detected within the scope of this inspection. They also depend, among other things, on the prevailing weather and inspection conditions.

intermediary: diepruefer.de GmbH / E.-Ruska-Ring 11 / D-07745 Jena

Das Gutachten wurde am 10.12.2020 um 08:55 Uhr erstellt.

(*1) – in Ordnung - alright = the signs of usage correspond to the age and mileage

(*2) – leichter Mangel - small damage = impairments regarding the value and appearance

(*3) – schwerer Mangel - severe damage = impairments regarding the functionality and security of the vehicle

(*4) – nicht vorhanden - non-existent = does not exist as a part of the vehicle

(*5) – nicht prüfbar - not assessable = could not be assessed properly due to the insufficient conditions

VL (v.l.) – front left

VR (v.r.) – front right

HL (h.l.) – back left

HR (h.r.) – back right

photo documentation



Bild 1: Front



Bild 2: Heck



Bild 3: Frontdiagonale rechts



Bild 4: Frontdiagonale links



Bild 5: Heckdiagonale rechts



Bild 6: Heckdiagonale links



Bild 7: Felge und Reifen v. r.



Bild 8: Felge und Reifen v. l.



Bild 9: Felge und Reifen h. r.



Bild 10: Felge und Reifen h. l.



Bild 11: Dach



Bild 12: Innenraum v. r.



Bild 13: Innenraum v. l.



Bild 14: Innenraum hinten



Bild 15: Motorraum



Bild 16: Instrumentenansicht



Bild 17: Armaturenbrett



Bild 18: Mittelkonsole



Bild 19: Kilometerstand



Bild 20: Fz.-Ident-Nr.



Bild 21: Mangel / Schaden – Karosserie Sicht - Stoßfänger vorn, leicht geschürft; leichter Steinschlag



Bild 22: Unterboden



Bild 23: Unterboden




Bild 24: Unterboden



Bild 25: Fahrzeugschein/ Fahrzeugbrief/ COC-Zertifikat



Bild 26: Dokumente/Schlüssel




Bild 31: Fahrzeugschein/ Fahrzeugbrief/ COC-Zertifikat




Bild 32: Ölzettel




Bild 33: Ölzettel




Bild 34: Mangel / Schaden – Karosserie Sicht - Motorhaube, Steinschlag; leichter Kratzer (poliert)




Bild 35: Mangel / Schaden – Karosserie Sicht - Motorhaube, Steinschlag; leichter Kratzer (poliert)



Bild 36: Mangel / Schaden – Karosserie Sicht - Stoßfänger vorn, leicht geschürft; leichter Steinschlag



Bild 37: Mangel / Schaden – Außen - Felgen, VR, VL, HR geschürft




Bild 38: Mangel / Schaden – Außen - Felgen, VR, VL, HR geschürft



Bild 39: Koffer-/Laderaum



Bild 40: Ölzettel – nicht vorhanden

The photo documentation contains 40 pictures.

VIN - Abfrageprotokoll

Fzg-Ident-Nr.:	W02052 Mercedes-Benz	Datum: 09.12.2020
Hersteller	R -Klasse (BM 251)(09.2005->)	
Haupttyp	R 350 L 4-Matic (251.165)	
Untertyp		
Herstellercode:		
Motorkennung:		
Getriebekennung:		
SilverDAT identifyCODE ®:	0	
Bauzeit:	10.	(xxxx)
Motorvariante:	Motor 3,5 Ltr. - 200 kW V6 KAT	

Ausstattung:

Bezeichnung

1. Ergzung zu Code 226

2. Ergzung zu Code 226

2. Ergzung zu Code 226

5+2 Sitzer

AEJ 09/1

AGGREGAT FUER TESTFAHRZEUG

AIRBAGSCHILD - DEUTSCH/ENGLISCH

ALLRADFAHRZEUGE

AMG Styling

AMG Styling

Abbiegelicht

Abgasreinigung mit EU5 Technik

Abstandsregeltempomat

Abstandsregeltempomat

Adaptives Bremslicht blinkend

Ascher-Paket

Ascher-Paket

Aun- u. Innenspiegel autom. abblendbar

Aun- u. Innenspiegel autom. abblendbar

Aun- u. Innenspiegel autom. abblendbar

Aunspiegel li.u.re.el.heranklapptbar

Automatikgetriebe 7G-TRONIC

BAUREIHE 251

BEDIENUNGSANLEITUNG U.WARTUNGSHEFT-DEUTSCH

BUNDESREPUBLIK DEUTSCHLAND

Batterie m. größerer Kapazität

Bi-Xenon mit Kurvenlicht Rechtsverkehr
COMAND APS mit DVD-Wechsler
COMAND APS mit DVD-Wechsler
Chrom-Paket
DEUTSCHLAND
DVD-PLAYER MIT REGIONAL-CODE 2 EUROPA,JAPAN
Direktlenkung
Direktlenkung
EASY-PACK-Laderaumabdeckung
Fahrwerk mit Stahl-/ Luftfederung
Fuatten Velours
GETRIEBE AUTOMATISCH
GETRIEBECODE AUSFUEHRUNG 06
HINTERACHSE
HUBRAUM 3,5 LITER
Hinweis für Sonderaggregate
Identifizierungssch. unter Windschutzscheibe
Innenraum-Lichtpaket
Innenraum-Lichtpaket
KFZ-Brief Wegfall u. ohne ABE-Nr.
Klimatisierungsautomatik
Klimatisierungsautomatik
Klimatisierungsautomatik
Komfort-Telefonie
Komfort-Telefonie
Komfort-Telefonie
LEDER
LEDER GRAU / SCHIEFERGRAU
LIMOUSINE LANG
LINKS-LENKUNG
LMR 5-Doppelspeichen-Design 'Stern' 18"
LMR 5-Doppelspeichen-Design 'Stern' 18"
MANUELL TERMINGESTEUERTES FAHRZEUG
MB-MOBILO MIT DSB UND GGD
Media Interface inkl. Consumer-Kabel Kit
Multifunktionslenkrad in Leder Nappa
Multifunktionslenkrad in Leder Nappa
Multifunktionslenkrad in Leder Nappa
Multifunktionslenkrad in Leder Nappa
NAG2 MIT DSM
Neck-Pro-Kopfstzen, 1.Sitzreihe
PARKTRONIC System (PTS)
PRE-SAFE -System
Produktschutz f. Lack - Konservierung Versandfzg.

Produktschutz f. Versandfahrzg. mit Transporten
Reifendruckkontrolle
Rkfahrkamera
S - SCHALTPLATTE MIT VGS 3*
SHIFT BY WIRE
SONDERTESTWAGEN
SPEED+ - LOADINDEX 105 W
SPRACHE KOMBIINSTRUMENT - DEUTSCH
STEUERCODE FUER SERVICEINTERVALL 25000 KM
STEUERCODE WERK TUSCALOOSA
STEUERCODE WERK TUSCALOOSA
Scheibenwaschanlage beheizt
Scheinwerferreinigungsanlage
Seitenfenster hinten elektr. ausstellbar
Sicherheitsnetz f Gepkraumabdeckung
Sicherheitsnetz f Gepkraumabdeckung
Sidebag im Fond links und rechts
Sitzheizung Vordersitze
Sommerreifen
Spiegel-Paket
TENORITGRAU, METALLICLACK
V6-OTTOMOTOR M272
VORDERACHSHAELFTE LINKS
VORDERACHSHAELFTE RECHTS
Vordersitze elektrisch verstellbar
WANDLER MIT ABWEICHENDER KENN LINIE
WD Glas dunkel gett, Heck-/Seitenfenst. hi.
WD und IR reflektierendes Verbundglas
Zierteile Holzausfrung Pappel-Vogelaugen-Optik
Zierteile Holzausfrung Pappel-Vogelaugen-Optik

Farben:

Bezeichnung

tenoritgrau metallic
Leder alpakagrau