

Customer	Vehicle Owner	responsible Vehicle expert

inspection conditions	
support of the car seller	yes
weather conditions	dry
lighting conditions	daylight
vehicle surface	dry/clean
access to the vehicle	accessible from all sites
underbody panelling	available - undamaged
lifting platform / pothole / ramp	available and used
test drive completed	yes
Why wasn't it possible to do a test drive?	

vehicle					
vehicle identification number (VIN)	WBALM31000E4546	producer	BMW	model	Z4
construction/design type	coupé	number of doors	2 doors	gearbox	automatic transmission
next general inspection	05/20	pollutant class	Euro 5	motor fuel	petrol
mileage	63.378	first registration	2011	previous owners	2
previous usage	one-year-old car	performance in kW	150	cubic capacity	2497
keys	2 with remote control	colour	schwarz	type of automotive paint/lacquer	metallic
smell	alright	seats	2		

● alright (*1) ● small damage (*2) ● severe damage (*3) ● non-existent (*4) ● not assessable (*5)

vehicle documents	
● permits	non-existent/ was not available at the time of evaluation
● registration cert. Pt 1 / vehicle licence	original
● registration cert. Pt 2 / vehicle registration document	original
● service booklet	original
● log book/ radio code/ navigation software (CD)	original
● type approval	original
● HU/AU report	original

customer service/repairs			
date	mileage	inspection mode	Who did the servicing?
05.04.2013	18	small inspection	authorized garage
05.05.2015	35	complete vehicle inspection	authorized garage
05.05.2017	47	small inspection	authorized garage
04.06.2019	63	complete vehicle inspection	authorized garage

remarks regarding customer services/repairs

tires	producer	usage	size	profile thickness in mm	remark
● front left mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● front right mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● back left mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	roadworthy
● back right mounted	Bridgestone Potenza	summer tyres	225/35 R 19 88Y	6,0	porous
● spare wheel					

paint thickness	paint layer thickness in µm	condition
● engine bonnet	135	stone chipping
● mudguard front right	110	
● door front/right	110	
● door back/right		
● side wall/fender back/right	105	alright
● rear lid	110	
● fender back left	150	repaired damage caused by an accident
● door back/left		
● door front/left	1135	repaired damage caused by an accident
● mudguard front left	130	repaired damage caused by an accident
● roof	125	alright

state of the vehicle at the time of inspection - interior - interior visual inspection	
● security belts	
● steering wheel	
● instruments/ dashboard	
● air conditioner	
● heater/ air filter	
● sunroof/electric hood	
● operating elements	
● window lifter	
● rear view mirror	
● seats in front	
● seats behind	
● storage places/ gloves compartement	
● radio	
● floor covering	
● interior disguising	
● headliners	
● signal horn	

state of the vehicle at the time of inspection - lights

☒ headlight	
☒ backlight	
☒ brakelight	
☒ reversing light	
☒ indicator	
☒ hazard lights	
☒ fog lamp	
☒ Abblendlicht	
☒ interior lights	
☒ daytime running lamp	

state of the vehicle at the time of inspection - exterior

☒ rims	VR, VL, HR geschürft
☒ sealings	
☒ windshield	
☒ window glazing	
☒ windscreen wiper	
☒ car locks/ central locking system	
☒ general state of automotive paint	
☒ recognizable repainting	
☒ attached parts	
☒ exterior mirror	

state of the vehicle at the time of inspection - exterior cover

☒ front bumpers	leicht geschürft; leichter Steinschlag
☒ grill	
☒ engine bonnet	Steinschlag; leichter Kratzer (poliert)
☒ roof	in Ordnung
☒ rear lid	
☒ side wall/fender back/left	reparierter Unfallschaden
☐ door back/left	nicht vorhanden
☒ door sill left	
☒ door front/left	reparierter Unfallschaden
☒ mudguard front left	reparierter Unfallschaden
☒ mudguard front right	
☒ door front/right	
☒ door sill right	
☐ door back/right	nicht vorhanden
☒ side wall/fender back/right	
☒ back bumpers	
☒ gap dimensions	

state of the vehicle at the time of inspection - underbody view (as far as testable)	
☒ steering linkage	
☒ steering gear	
☒ control arm	
☒ wheel suspension	
☒ anti-roll bar front/back	
☒ shock absorber	
☒ springs	
☒ wheel bearing	
☒ brake cables/hose	
☒ brake disc	
☒ brake pad	
☒ brake line	
☒ brake abrasion	
☒ condition of the exhaust system	
☒ exhaust manifold	
☒ oil density gear	
☒ oil density engine	
☒ oil density differential	
☒ state of the underbody (general)	

state of the vehicle at the time of inspection - engine compartment view	
☒ motor oil state	
☒ brake fluid - state	
☒ cooler status	
☒ fuel system	
☒ battery casing/ fixing	

state of the vehicle at the time of inspection - test run of the propulsion engine	
☒ starter	
☐ clutch	nicht vorhanden
☒ motor running	
☒ functioning of the instruments	
☒ conspicuous noises	
☒ conspicuous noises timing chain	

conditions during the test drive	
was carried out on	13:00
highest speed achieved	50
was carried out in/on the	city
conspicuous features?	keine

state of the vehicle at the time of inspection - test drive	
● clutch	Nicht prüfbar
● steering	
● gearbox	
● conspicuous noises	
● functioning of instruments	
● directional stability	
● brake system responsivity	
● load change	
● motor running	
● braking action	
● accelerator	
● gear change	

error in instrument cluster
No failures were displayed in the electronic instrument cluster.

existing / known accident damage
The following traces of accidents were found: Seitenwand-Kotflügel h. l. - reparierter Unfallschaden Tür v. l. - reparierter Unfallschaden Kotflügel v. l. - reparierter Unfallschaden

Conclusion of the expert:
The following damages were identified: Außen - Felgen - leichter Mangel - VR, VL, HR geschürft Karosserie Sicht - Stoßfänger vorn - leichter Mangel - leicht geschürft; leichter Steinschlag Karosserie Sicht - Motorhaube - leichter Mangel - Steinschlag; leichter Kratzer (poliert) No impairment of road safety was found. The vehicle possesses traces of use corresponding to the age and mileage.

The inspection was carried out without exposing the assemblies or dismantling work. There remains a risk of hidden defects or accidental damage.

Important: The condition report of the vehicle was prepared to the best of the expert's knowledge and belief at the time of the inspection under the given possibilities. The report does not establish any liability towards the inspector nor does it contain any guarantee for the buyer or seller. All components/groups not expressly listed will not be assessed as part of the inspection. The inspection is always carried out without disassembly work or disassembly of parts. Not all conceivable load and operating conditions can be achieved within the scope of the visual and functional inspection of the individual components and the test run and therefore not all possible existing defects can be detected within the scope of this inspection. They also depend, among other things, on the prevailing weather and inspection conditions.

intermediary: diepruefer.de GmbH / Schillerstraße 1 / 07745 Jena

Das Gutachten wurde am 06.06.2019 um 10:54 Uhr erstellt.

(*1) – In Ordnung - alright = the signs of usage correspond to the age and mileage

(*2) – leichter Mangel- small damage = impairments regarding the value and appearance

(*3) – schwerer Mangel - severe damage = impairments regarding the functionality and security of the vehicle

(*4) – nicht vorhanden - non-existent = does not exist as a part of the vehicle

(*5) – nicht prüfbar - not assessable = could not be assessed properly due to the insufficient conditions

VL (v.l.) – front left

VR (v.r.) – front right

HL (h.l.) – back left

HR (h.r.) – back right



Bild 1: Front



Bild 2: Heck



Bild 3: Frontdiagonale rechts



Bild 4: Frontdiagonale links



Bild 5: Heckdiagonale rechts



Bild 6: Heckdiagonale links



Bild 7: Felge und Reifen v. r.



Bild 8: Felge und Reifen v. l.



Bild 9: Felge und Reifen h. r.



Bild 10: Felge und Reifen h. l.



Bild 11: Dach



Bild 12: Innenraum v. r.



Bild 13: Innenraum v. l.



Bild 14: Innenraum hinten



Bild 15: Motorraum



Bild 16: Instrumentenansicht



Bild 17: Armaturenbrett



Bild 18: Mittelkonsole



Bild 19: Kilometerstand



Bild 20: Fz.-Ident-Nr.



Bild 21: Mangel / Schaden – Karosserie Sicht - Stoßfänger vorn, leicht geschürft; leichter Steinschlag



Bild 22: Unterboden



Bild 23: Unterboden



Bild 24: Unterboden



Bild 25: Fahrzeugschein/ Fahrzeugbrief/ COC-Zertifikat



Bild 26: Dokumente/Schlüssel




Bild 31: Fahrzeugschein/ Fahrzeugbrief/ COC-Zertifikat



Bild 32: Ölzettel




Bild 33: Ölzettel



Bild 34: Mangel / Schaden – Karosserie Sicht - Motorhaube, Steinschlag; leichter Kratzer (poliert)




Bild 35: Mangel / Schaden – Karosserie Sicht - Motorhaube, Steinschlag; leichter Kratzer (poliert)



Bild 36: Mangel / Schaden – Karosserie Sicht - Stoßfänger vorn, leicht geschürft; leichter Steinschlag



Bild 37: Mangel / Schaden – Außen - Felgen, VR, VL, HR geschürft



Bild 38: Mangel / Schaden – Außen - Felgen, VR, VL, HR geschürft



Bild 39: Koffer-/Laderaum



Bild 40: Ölzettel – nicht vorhanden

The photo documentation contains 40 pictures.